



Photo 1: View of the project area from the southern corner facing center.



Photo 2: View of the southwestern portion of the project area from the southern corner facing northwestward. Revegetation is largely comprised of western wheatgrass (*Pascopyrum smithii*) and dropseed (*Sporobolus* sp.) along the edges of the working area.



Photo 3: View of the southeastern portion of the project area from the southern corner facing northeastward.



Photo 4: View of the northeastern portion of the project area from the eastern corner facing northwestward.



Photo 5: View of junk in the southeastern portion of the project area.



Photo 6: View of more debris within the southeastern portion of the project area.



Photo 7: View of area in the southwestern portion of the project area that appears to be eroding.