

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/11/2017

Submitted Date:

04/25/2017

Document Number:

666803112**FIELD INSPECTION FORM**
 Loc ID 334591 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
266285	WELL	PR	06/01/2010	GW	045-09143	BJM 31-10D (J31NEB)	PR
266287	WELL	PR	08/24/2003	GW	045-09142	BJM 31-14A (J31NEB)	PR
266288	WELL	PR	08/24/2003	GW	045-09141	BJM 31-11C (J31NEB)	PR
266895	WELL	PR	10/09/2008	GW	045-09187	COUEY 31-7D (J31NEB)	PR
266897	WELL	PR	11/11/2013	GW	045-09188	BJM 31-6D (J31NEB)	PR
276413	WELL	PR	01/18/2005	GW	045-10449	BJM 31-10A (J31NEB)	PR
276414	WELL	PR	02/09/2006	GW	045-10448	BJM 31-16C (J31NEB)	PR
276415	WELL	PR	10/09/2008	GW	045-10447	BJM 31-11D (J31NEB)	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Plunger Lift

8

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

1

Comment:

Corrective Action:

Date:

Type: Vertical Heated Separator

8

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

1

Comment: [Chemical unit at wellhead](#)

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0				,
Comment:					
Corrective Action:					Date:

Paint

Condition

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
METHANOL	1	1000 GAL	STEEL AST		,	
Comment:		Centralized battery				
Corrective Action:						Date:
<u>Paint</u>						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	3	500 BBLs	STEEL AST		39.480679,-107.706296	
Comment:						
Corrective Action:						Date:
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:						Date:
<u>Venting:</u>						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
<u>Flaring:</u>						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities									
Facility ID:	266285	Type:	WELL	API Number:	045-09143	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	266287	Type:	WELL	API Number:	045-09142	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	266288	Type:	WELL	API Number:	045-09141	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	266895	Type:	WELL	API Number:	045-09187	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	266897	Type:	WELL	API Number:	045-09188	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	276413	Type:	WELL	API Number:	045-10449	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	276414	Type:	WELL	API Number:	045-10448	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	276415	Type:	WELL	API Number:	045-10447	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			

--

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): NO	
Comment:	
Pilot:	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
		Gravel	Pass			
		Ditches	Pass			
		Culverts	Pass			
		Sediment Traps	Pass			
Berms	Pass					

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT