

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/12/2017

Submitted Date:

04/25/2017

Document Number:

666803115**FIELD INSPECTION FORM**

Loc ID 414522	Inspector Name: Murray, Richard	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 22 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: <u>10531</u> Name of Operator: <u>VANGUARD OPERATING LLC</u> Address: <u>5847 SAN FELIPE #3000</u> City: <u>HOUSTON</u> State: <u>TX</u> Zip: <u>77057</u>				

Contact Information:

Contact Name	Phone	Email	Comment
Axelsson, Aaron	970-230-0926	aaxelson@vnrlc.com	Sr. Production Foreman
Ghan, Scott		sghan@vnrlc.com	Sr. EH&S

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
415055	WELL	PR	12/09/2014	GW	045-18949	JOLLEY 21A-20-691	PR
415056	WELL	PR	08/26/2010	GW	045-18950	JOLLEY FED 11A-20-691	PR
415057	WELL	PR	10/05/2010	GW	045-18951	JOLLEY FED 11C-20-691	PR
415064	WELL	PR	09/02/2010	GW	045-18952	JOLLEY FED 22B-20-691	PR
415069	WELL	PR	08/14/2010	GW	045-18953	JOLLEY FED 12D-20-691	PR
415072	WELL	PR	09/02/2010	GW	045-18954	JOLLEY FED 12A-20-691	PR
415073	WELL	PR	09/02/2010	GW	045-18955	JOLLEY FED 12B-20-691	PR
415075	WELL	PR	10/05/2010	GW	045-18956	JOLLEY 21D-20-691	PR
415076	WELL	PR	10/05/2010	GW	045-18957	JOLLEY FED 11D-20-691	PR
415084	WELL	PR	08/12/2010	GW	045-18958	JOLLEY FED 12C-20-691	PR
415085	WELL	PR	08/14/2010	GW	045-18959	JOLLEY FED 11B-20-691	PR
415086	WELL	PR	07/21/2010	GW	045-18960	JOLLEY 21B-20-691	PR
415087	WELL	PR	09/02/2010	GW	045-18961	JOLLEY FED 22A-20-691	PR
415090	WELL	PR	10/05/2010	GW	045-18962	JOLLEY 21C-20-691	PR
415091	WELL	PR	07/21/2010	GW	045-18963	JOLLEY FED 22C-20-691	PR
415092	WELL	PR	08/27/2010	GW	045-18964	JOLLEY FED 22D-20-691	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Emission Control Device

1

Comment:

Corrective Action:

Date:

Type: Pig Station

1

Comment:

Corrective Action:

Date:

Type: Plunger Lift

16

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

5

Comment: Chemical units at wellhead

Corrective Action:

Date:

Type: Horizontal Heated Separator

16

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	500 BBLS	STEEL AST		39.517512,-107.582790
Comment: temporary tank at wellhead					
Corrective Action:					Date:

Paint

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Inspector Name: Murray, Richard

Other					
Comment:	No berm				
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	10	500 BBLs	STEEL AST		39.518097,-107.583147
Comment:					
Corrective Action:					Date:
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No	YES				
Comment:	Bradenhead valves open				
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities									
Facility ID:	415055	Type:	WELL	API Number:	045-18949	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	415056	Type:	WELL	API Number:	045-18950	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	415057	Type:	WELL	API Number:	045-18951	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	415064	Type:	WELL	API Number:	045-18952	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	415069	Type:	WELL	API Number:	045-18953	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	415072	Type:	WELL	API Number:	045-18954	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	415073	Type:	WELL	API Number:	045-18955	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	415075	Type:	WELL	API Number:	045-18956	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			

Facility ID:	415076	Type:	WELL	API Number:	045-18957	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	415084	Type:	WELL	API Number:	045-18958	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	415085	Type:	WELL	API Number:	045-18959	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	415086	Type:	WELL	API Number:	045-18960	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	415087	Type:	WELL	API Number:	045-18961	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	415090	Type:	WELL	API Number:	045-18962	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	415091	Type:	WELL	API Number:	045-18963	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	415092	Type:	WELL	API Number:	045-18964	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			

--

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): YES	
Comment:	
Pilot: ON	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
		Ditches	Pass			
Waddles	Pass					
		Culverts	Pass			
Seeding	Pass					
Ditches	Pass					
		Check Dams	Pass			
Gravel	Pass					
		Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT