



**photo 1:** Facing west toward wellhead and pit.



**photo 2:** Facing northwest toward the cut-slope. Sediment is being deposited around the equipment.



**photo 3:** The doors of this shed are open and sediment deposition prevents them from being closed.



**photo 4:** There is a bucket which appears to be used as containment which is full of water.



**photo 5:** Facing east toward the C. Brown offsite pit.



**photo 6:** Noticed noxious weeds (Plumeless thistle) beginning to germinate in areas around the C. Brown offsite pit.