



**photo 1:** Facing southeast toward the location.



**photo 2:** Facing northwest toward the cut-slope.





**photo 3:** What appears to be last year's growth of noxious weeds (thistle) along the cut slope.



**photo 4:** Facing east toward the offsite pit.





**photo 5:** Facing west toward the offsite pit.



**photo 6:** Noticed noxious weeds (Scotch thistle) beginning to germinate in areas around the offsite pit.