

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/12/2017

Submitted Date:

04/26/2017

Document Number:

666803118**FIELD INSPECTION FORM**

Loc ID 417271	Inspector Name: Murray, Richard	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 10 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
<b>Operator Information:</b> OGCC Operator Number: <u>96850</u> Name of Operator: <u>TEP ROCKY MOUNTAIN LLC</u> Address: <u>PO BOX 370</u> City: <u>PARACHUTE</u> State: <u>CO</u> Zip: <u>81635</u>				

**Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		COGCCInspectionReports@terraep.com	Field Inspections
Freeman, Sarah		sarah.freeman@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
417329	WELL	PR	04/26/2012	GW	045-19478	Federal KP 23-18	PR
417330	WELL	PR	05/18/2012	GW	045-19479	Federal KP 322-18	PR
417337	WELL	PR	03/13/2012	GW	045-19485	Federal KP 333-18	PR
417338	WELL	PR	04/01/2012	GW	045-19486	Federal KP 332-18	PR
428213	WELL	XX	03/11/2014	LO	045-21443	FEDERAL KP 532-18	ND
428214	WELL	XX	03/11/2014	LO	045-21444	FEDERAL KP 423-18	ND
428215	WELL	XX	03/11/2014	LO	045-21445	FEDERAL KP 33-18	ND
428216	WELL	XX	03/11/2014	LO	045-21446	FEDERAL KP 522-18	ND
428217	WELL	XX	03/11/2014	LO	045-21447	FEDERAL KP 22-18	ND
428218	WELL	XX	03/11/2014	LO	045-21448	FEDERAL KP 32-18	ND
428219	WELL	XX	03/11/2014	LO	045-21449	FEDERAL KP 432-18	ND
428220	WELL	XX	03/11/2014	LO	045-21450	FEDERAL KP 422-18	ND
428223	WELL	XX	03/11/2014	LO	045-21451	FEDERAL KP 323-18	ND
428226	WELL	XX	03/11/2014	LO	045-21452	FEDERAL KP 531-18	ND

**General Comment:**

Drilling permits expired 5/17/16, Contact COGCC permit staff

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type	Area	Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Ancillary equipment

# 1

Comment: Chemical unit at wellhead

Corrective Action:

Date:

Type: Horizontal Heated Separator

# 4

Comment:

Corrective Action:

Date:

Type: Plunger Lift

# 4

Comment:

Corrective Action:

Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	300 BBLS	STEEL AST		,
Comment: Centralized battery					
Corrective Action:					Date:

**Paint**

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

**Berms**

Type	Capacity		Permeability (Wall)		Permeability (Base)		Maintenance			
Comment:										
Corrective Action:									Date:	
Contents		#	Capacity	Type		Tank ID		SE GPS		
CONDENSATE		4	300 BBLS	STEEL AST				39.526039,-107.596065		
Comment:		1-300 bbls tank labled out of service								

Corrective Action:		Date:		
<b>Paint</b>				
Condition	Adequate			
Other (Content)				
Other (Capacity)				
Other (Type)				
<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:
<b>Venting:</b>				
Yes/No	YES			
Comment:	Bradenhead valves open			
Corrective Action:				Date:
<b>Flaring:</b>				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities									
Facility ID:	417329	Type:	WELL	API Number:	045-19478	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	417330	Type:	WELL	API Number:	045-19479	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	417337	Type:	WELL	API Number:	045-19485	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	417338	Type:	WELL	API Number:	045-19486	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	428213	Type:	WELL	API Number:	045-21443	Status:	XX	Insp. Status:	ND
Facility ID:	428214	Type:	WELL	API Number:	045-21444	Status:	XX	Insp. Status:	ND
Facility ID:	428215	Type:	WELL	API Number:	045-21445	Status:	XX	Insp. Status:	ND
Facility ID:	428216	Type:	WELL	API Number:	045-21446	Status:	XX	Insp. Status:	ND
Facility ID:	428217	Type:	WELL	API Number:	045-21447	Status:	XX	Insp. Status:	ND
Facility ID:	428218	Type:	WELL	API Number:	045-21448	Status:	XX	Insp. Status:	ND
Facility ID:	428219	Type:	WELL	API Number:	045-21449	Status:	XX	Insp. Status:	ND
Facility ID:	428220	Type:	WELL	API Number:	045-21450	Status:	XX	Insp. Status:	ND
Facility ID:	428223	Type:	WELL	API Number:	045-21451	Status:	XX	Insp. Status:	ND
Facility ID:	428226	Type:	WELL	API Number:	045-21452	Status:	XX	Insp. Status:	ND

--

--

## Environmental

### Spill/Remediation:

Comment:

Corrective  
Action:

Date:

Emission Control Burner (ECB): NO

Comment:

Pilot:

Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
Seeding	Pass					
Slope Roughening	Pass					
Drains	Pass					
Rip Rap	Pass					
Gravel	Pass					
		Gravel	Pass			
Sediment Traps	Pass					
		Culverts	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT