

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

04/14/2017

Submitted Date:

04/26/2017

Document Number:

666803122**FIELD INSPECTION FORM**

Loc ID 335509	Inspector Name: Murray, Richard	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: <u>96850</u> Name of Operator: <u>TEP ROCKY MOUNTAIN LLC</u> Address: <u>PO BOX 370</u> City: <u>PARACHUTE</u> State: <u>CO</u> Zip: <u>81635</u>				Findings: <u>17</u> Number of Comments <u>0</u> Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
, Inspections		COGCCInspectionReports@terraep.com	Field Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
296866	WELL	PR	03/23/2009	GW	045-16184	JOHNSON RWF 434-30	PR
296892	WELL	PR	06/30/2009	GW	045-16192	JOHNSON RWF 534-30	PR
296893	WELL	PR	07/03/2008	GW	045-16193	JOHNSON RWF 334-30	PR
296894	WELL	PR	03/01/2009	GW	045-16194	JOHNSON RWF 533-30	PR
296895	WELL	PR	02/28/2009	GW	045-16195	JOHNSON RWF 34-30	PR
296896	WELL	PR	07/03/2008	GW	045-16196	JOHNSON RWF 433-30	PR
296897	WELL	PR	04/30/2009	GW	045-16197	JOHNSON RWF 443-30	PR
296898	WELL	PR	04/30/2009	GW	045-16198	JOHNSON RWF 543-30	PR
296899	WELL	PR	07/03/2008	GW	045-16199	JOHNSON RWF 343-30	PR
296900	WELL	PR	03/31/2009	GW	045-16200	JOHNSON RWF 43-30	PR
296901	WELL	PR	05/20/2009	GW	045-16201	JOHNSON RWF 442-30	PR
296902	WELL	PR	06/30/2009	GW	045-16202	JOHNSON RWF 444-30	PR
296903	WELL	PR	04/30/2009	GW	045-16203	JOHNSON RWF 643-30	PR
296904	WELL	PR	06/30/2009	GW	045-16204	JOHNSON RWF 44-30	PR
296905	WELL	PR	06/30/2009	GW	045-16205	JOHNSON RWF 344-30	PR

General Comment:[Facilities on location ID 335487](#)

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Plunger Lift	# 15		corrective date
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities						
Facility ID:	296866	Type:	WELL	API Number: 045-16184	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	296892	Type:	WELL	API Number: 045-16192	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	296893	Type:	WELL	API Number: 045-16193	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	296894	Type:	WELL	API Number: 045-16194	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	296895	Type:	WELL	API Number: 045-16195	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	296896	Type:	WELL	API Number: 045-16196	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	296897	Type:	WELL	API Number: 045-16197	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	296898	Type:	WELL	API Number: 045-16198	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Plunger lift					
Corrective Action:						Date:

Facility ID:	296899	Type:	WELL	API Number:	045-16199	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	296900	Type:	WELL	API Number:	045-16200	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	296901	Type:	WELL	API Number:	045-16201	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	296902	Type:	WELL	API Number:	045-16202	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	296903	Type:	WELL	API Number:	045-16203	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	296904	Type:	WELL	API Number:	045-16204	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	296905	Type:	WELL	API Number:	045-16205	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
		Gravel	Pass			
		Ditches	Pass			
Ditches	Pass					
		Culverts	Pass			
Seeding	Pass					

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT