

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/06/2017

Submitted Date:

04/20/2017

Document Number:

672500493**FIELD INSPECTION FORM**

Loc ID 449174 Inspector Name: Gomez, Jason On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10110Name of Operator: GREAT WESTERN OPERATING COMPANY LLCAddress: 1801 BROADWAY #500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspections@gwogco.com	All Inspections
Precup, Jim		james.precup@state.co.us	
Adamczyk, Megan		megan.adamczyk@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
449164	WELL	XX	02/09/2017		001-09993	Ocho LD 17-367HC	DG
449165	WELL	XX	02/09/2017		001-09994	Ocho LD 17-367HN	DG
449167	WELL	XX	02/09/2017		001-09996	Ocho LD 17-364HC	DG
449172	WELL	XX	02/09/2017		001-10001	Ocho LD 17-365HN	DG

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Ancillary equipment

#

Comment:

APPROX 28' SOUND WALLS ON WEST, NORTH AND EAST SIDE OF LOCATION
DIRT BERM ON SW AND SOUTH OF LOCATION

Corrective Action:

Date:

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 449164 Type: WELL API Number: 001-09993 Status: XX Insp. Status: DG

Complaint

Comment:

Corrective Action:

Date:

Facility ID: 449165 Type: WELL API Number: 001-09994 Status: XX Insp. Status: DG

Complaint

Comment:

Complaint #: 200441281

Field Inspector Assigned: Jason E. Gomez

Complaint Received:

Date: 4-6-2017 Time 1030 Hrs

Contacted by Inspector:

Date: 4-6-2017 Time 1100 Hrs

Well Number#: Location #: 449174

Inspection Document #: 672500493

Complainant: Melissa McGinnes Phone: 720-209-4800

Address: 6051 E 160th Place, Brighton CO 80602

Nature of complaint: Noise/Lights/Odors

Field Inspector Actions:

On 4-6-2017, I was contacted by James Precup NE supervisor of the COGCC in reference to a complaint at the residence of the complainants Melissa McGinnes 6051 E. 160th Pl, Brighton Colorado.

I contacted the complainant who indicated she was experiencing a noise coming from the drilling rig located to the SE of her home, she described the noise has something she could hear like a low drowning sound but she said she could also fill the noise. She indicated the vibrations had caused things to shake off the walls in one of the bedrooms upstairs.

I performed a complete site inspection of the location on 4-6-2017. At the time of inspection, I also performed a sound study approx. 25' from the SE corner of the complainant's home toward the drilling rig. I reviewed location records, which did not show any abnormal drilling conditions at the time of the complaints. All lighting on the rig were pointed down and toward the center of the location at the time of the inspection see inspections Doc#672500493 for attached sound study performed at complainants residence.

Great Western Operating Company representative Scot Donato indicated a third party sound study would be conducted on 4-6-2017, and GW would supply the COGCC with those results.

All information reviewed and site inspection as well as sound study information were submitted to the complaint specialist for further review.

No violations of COGCC rules were observed at the time of the inspection.

Corrective Action:

Date:

Well Drilling

Rig:	Rig Name: <u>PRECISION RIG 460</u>	Pusher/Rig Manager: <u>MARVIN</u>
	Permit Posted: <u>Yes</u>	Access Sign: <u>Yes</u>
Well Control Equipment:		
	Pipe Ram: <u>YES</u>	Blind Ram: <u>YES</u> Hydril Type: <u>YES</u>
	Pressure Test BOP: <u>Pass</u>	Test Pressure PSI: <u> </u> Safety Plan: <u>YES</u>
Drill Fluids Management:		
	Lined Pit: <u> </u>	Unlined Pit: <u> </u> Closed Loop: <u>YES</u> Semi-Closed Loop: <u> </u>
	Multi-Well: <u>YES</u>	Disposal Location: <u>WASTE MANAGEMENT</u>
	<u>Comment:</u>	<div></div>
	<u>Corrective Action:</u>	<div></div> Date: <u> </u>

Facility ID: <u>449167</u>	Type: <u>WELL</u>	API Number: <u>001-09996</u>	Status: <u>XX</u>	Insp. Status: <u>DG</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

Facility ID: <u>449172</u>	Type: <u>WELL</u>	API Number: <u>001-10001</u>	Status: <u>XX</u>	Insp. Status: <u>DG</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Compaction	Pass	Covering Materials	Pass	
Gravel	Pass					
Ditches	Pass			Vehicle Tracking	Pass	
Mulching	Pass					
Slope Roughening	Pass					
Silt Fences	Pass					
Compaction	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401264538	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4128775
672500494	SOUND STUDY	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4128568
672500495	Sound study Location photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4128569
672500515	GREAT WESTERN SOUND STUDY RESULTS AFTER NEW MITTIAGATION	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4128570