

Inspection Photos

04/27/2017

Operator: Diversified Operating Corp #24461

Location ID: 408223

Inspection Doc. Number: 682501949

Weld County, CO

SESW Section 21 T8N R58W

Aaron Trujillo

Reclamation Specialist

COGCC



Inspection Photos
Operator: Diversified
Location ID: 408223



Photo 1: Photo of GPS verifying location.

Inspection Photos
Operator: Diversified
Location ID: 408223



Photo 3: Photo taken from the location. Photo shows areas of the location that have not achieved total perennial, non-invasive uniform plant cover of at least eighty (80) percent of pre-disturbance or reference area levels. Unable to find evidence that additional reclamation activities have occurred.



Photo 4: Photo taken from the location. Photo shows areas of the location that have not achieved total perennial, non-invasive uniform plant cover of at least eighty (80) percent of pre-disturbance or reference area levels. Unable to find evidence that additional reclamation activities have occurred.



Photo 4: Photo taken from the location. Photo shows areas of the location that have not achieved total perennial, non-invasive uniform plant cover of at least eighty (80) percent of pre-disturbance or reference area levels. Unable to find evidence that additional reclamation activities have occurred. 6 foot measuring stick for reference.



Photo 5: Photo taken from the adjacent reference area. Photo shows vegetation over the reference area to visually compare to vegetation over reclamation area. Vegetations in reference area appears to be predominantly western wheat.