

# Inspection Photos

04/27/2017

Operator: Diversified Operating Corp #24461

Location ID: 408318

Inspection Doc. Number: 682501954

Weld County, CO

NENE Section 20 T8N R58W

Aaron Trujillo

Reclamation Specialist

COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Operator: Diversified  
Location ID: 408318



**Photo 1:** Photo of GPS verifying location.

Inspection Photos  
Operator: Diversified  
Location ID: 408318



**Photo 2:** Photo taken from the north end of the location, facing southeast. Photo shows large areas of the location that remain unvegetated and unstabilized. No evidence that reclamation activities had taken place.



**Photo 3:** Photo taken from the north end of the location. Photo shows large areas of the location that remain unvegetated and unstabilized. No evidence that reclamation activities had taken place. Hat for reference.

Inspection Photos  
Operator: Diversified  
Location ID: 408318



**Photo 2:** Photo taken from the north end of the location, facing southeast. Photo shows large areas of the location that remain unvegetated and unstabilized. No evidence that reclamation activities had taken place.



**Photo 3:** Photo taken from the south end of the location. Photo shows pipe sticking out of ground.