


## Inspection Photos

Location Number: 449028



Overhead view. Anadarko gas plant to southeast of drilling location.



Drill Rig from location entrance

**Inspection Photos**  
**Location Number: 449028**



**Covered chemical storage on south side of location.**



**Lights directed down into location.**



**Inspection Photos**  
**Location Number: 449028**



**Storm Water ditch on north side of location.**



**Track pad at location entrance**

Inspection Photos  
Location Number: 449028



**Modular sanitation on skid with living quarters.**