

Inspection Photos

Location Number: 449186



Location Entrance from
west



Stormwater BMP, Retention and
Waddles at Entrance

Inspection Photos

Location Number: 449186



Secondary Containment - Sanitation



Secondary Containment – Potable
Water and Waste

Inspection Photos

Location Number: 449186



Curtained Container – Chemical Storage



Emission Box Burner, Expandable



Inspection Photos

Location Number: 449186



Diesel Double Wall – Secondary
Containment

Storm water ditch on east side



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Number: 449186

