

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/28/2017

Submitted Date:

04/28/2017

Document Number:

674005151**FIELD INSPECTION FORM**

Loc ID 449025 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		COGCCinspections@Anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
449024	WELL	DG	03/11/2017		123-44119	CHICA 35N-14HZ	DG
449026	WELL	DG	03/08/2017		123-44120	CHICA 31C-23HZ	DG
449027	WELL	DG	03/10/2017		123-44121	CHICA 4N2-23HZ	DG
449028	WELL	DG	03/12/2017		123-44122	CHICA 35N2-14HZ	DG
449029	WELL	DG	03/09/2017		123-44123	CHICA 4N-23HZ	DG

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	OTHER		
Comment:	Location Entrance		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	Sound wall on north and west side of location.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 449024 Type: WELL API Number: 123-44119 Status: DG Insp. Status: DG

Well Drilling

Rig: Rig Name: Precision Pusher/Rig Manager: _____
 Permit Posted: Yes Access Sign: Yes

Well Control Equipment:

Pipe Ram: YES Blind Ram: YES Hydril Type: YES
 Pressure Test BOP: Pass Test Pressure PSI: 5000 Safety Plan: YES

Drill Fluids**Management:**

Lined Pit: _____ Unlined Pit: _____ Closed Loop: YES Semi-Closed Loop: YES
 Multi-Well: YES Disposal Location: _____

Comment: Cuttings hauled off location to Kerr Mckee recycling facility
Safety Plan posted in company office.

Corrective Action: _____ Date: _____

Facility ID: 449026 Type: WELL API Number: 123-44120 Status: DG Insp. Status: DG

Well Drilling

Rig: Rig Name: _____ Pusher/Rig Manager: _____
 Permit Posted: _____ Access Sign: _____

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
 Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids**Management:**

Lined Pit: _____ Unlined Pit: _____ Closed Loop: _____ Semi-Closed Loop: _____
 Multi-Well: _____ Disposal Location: _____

Comment: _____

Corrective Action: _____ Date: _____

Facility ID: 449027 Type: WELL API Number: 123-44121 Status: DG Insp. Status: DG

Well Drilling

Rig: Rig Name: _____ Pusher/Rig Manager: _____
 Permit Posted: _____ Access Sign: _____

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
 Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids**Management:**

Lined Pit: _____ Unlined Pit: _____ Closed Loop: _____ Semi-Closed Loop: _____
 Multi-Well: _____ Disposal Location: _____

Comment: Drilling at 10,000 feet.

Corrective Action: _____ Date: _____

Facility ID: 449028	Type: WELL	API Number: 123-44122	Status: DG	Insp. Status: DG
---------------------	------------	-----------------------	------------	------------------

Well Drilling

Rig: Rig Name: _____ Pusher/Rig Manager: _____
 Permit Posted: _____ Access Sign: _____

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
 Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids Management:

Lined Pit: _____ Unlined Pit: _____ Closed Loop: _____ Semi-Closed Loop: _____
 Multi-Well: _____ Disposal Location: _____
 Comment: _____
 Corrective Action: _____ Date: _____

Facility ID: 449029	Type: WELL	API Number: 123-44123	Status: DG	Insp. Status: DG
---------------------	------------	-----------------------	------------	------------------

Well Drilling

Rig: Rig Name: _____ Pusher/Rig Manager: _____
 Permit Posted: _____ Access Sign: _____

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
 Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids Management:

Lined Pit: _____ Unlined Pit: _____ Closed Loop: _____ Semi-Closed Loop: _____
 Multi-Well: _____ Disposal Location: _____
 Comment: _____
 Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
Routine drilling inspection. Company representative on location: Jackie McKinley	carlilec	04/28/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
674005152	Location Photos	http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4136375