

CX-7 Control Measure Improvements Along Access Road – Completed 4/17/17



Photo 1: Control measure improvements installed adjacent to farm field and CX-7 access road. Swales and ditch have been re-seeded.



Photo 2: Control measure improvements to control ditch cutting have been installed on CX-7 access road.

CX-7 Control Measure Improvements Along Access Road – Completed 4/17/17



Photo 3: Slope has been re-seeded and blanketed on CX-7 access road.