

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/24/2017

Submitted Date:

05/02/2017

Document Number:

666803134**FIELD INSPECTION FORM**

Loc ID 334388 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1400City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
, Laramie		cogccnotifications@laramie-energy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
297765	WELL	PR	12/20/2010	GW	045-16960	JOHNSON FED. 5-10C	PR
297766	WELL	PR	03/01/2014	GW	045-16961	JOHNSON 5-02B	PR
297767	WELL	PR	08/14/2008	GW	045-16962	JOHNSON FED. 5-15B	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Chemical unit at wellhead		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	OTHER	STEEL AST		,
Comment:	Centralized battery				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	500gal	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Comment:							
Corrective Action:							Date:
Contents	#	Capacity	Type	Tank ID	SE GPS		
CONDENSATE	3	400 BBLs	STEEL AST		39.397322,-107.797269		
Comment:							
Corrective Action:							Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:		Date:		

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 297765	Type: WELL	API Number: 045-16960	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Plunger lift			
Corrective Action:			Date:	
Facility ID: 297766	Type: WELL	API Number: 045-16961	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Plunger lift			
Corrective Action:			Date:	
Facility ID: 297767	Type: WELL	API Number: 045-16962	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Plunger lift			
Corrective Action:			Date:	

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): YES	
Comment:	ECB is lock out tag out
Pilot: OFF	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Sediment Traps	Pass					
		Ditches	Pass			
		Sediment Traps	Pass			
Berms	Pass					
Gravel	Pass					
Ditches	Pass					
		Culverts	Pass			
		Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT