

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/24/2017

Submitted Date:

05/02/2017

Document Number:

666803135**FIELD INSPECTION FORM**
 Loc ID 334423 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1400City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
, Laramie		cogccnotifications@laramie-energy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
297283	WELL	PR	10/16/2013	GW	045-16377	JOHNSON 5-05A	PR
297284	WELL	PR	10/17/2013	GW	045-16378	JOHNSON 5-06D	PR
297304	WELL	PR	10/14/2013	GW	045-16383	JOHNSON FED. 5-04B	PR
425799	WELL	XX	10/12/2011	LO	045-21064	Johnson Fed. 31-08A	ND

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Emission Control Device

1

Comment:

Corrective Action:

Date:

Type: Pig Station

1

Comment:

Corrective Action:

Date:

Type: Plunger Lift

3

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

0

Comment:

Corrective Action:

Date:

Type: Vertical Heated Separator

3

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	OTHER	STEEL AST		,
Comment: Centralized battery					
Corrective Action:					Date:

Paint

Condition Adequate

Other (Content)

Other (Capacity) 500gal

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Comment:						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	400 BBLs	STEEL AST		39.398981,-107.805784	
Comment:						
Corrective Action:						Date:
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:						Date:
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
Flaring:						
Type						
Comment:						
Corrective Action:					Date:	

Inspected FacilitiesFacility ID: 297283 Type: WELL API Number: 045-16377 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger liftCorrective Action: Date: Facility ID: 297284 Type: WELL API Number: 045-16378 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger liftCorrective Action: Date: Facility ID: 297304 Type: WELL API Number: 045-16383 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger liftCorrective Action: Date: Facility ID: 425799 Type: WELL API Number: 045-21064 Status: XX Insp. Status: ND**Workover**Comment: Drilling permit expired 10/11/2013Corrective Action: Date:

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON

Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
		Sediment Traps	Pass			
		Ditches	Pass			
		Gravel	Pass			
Gravel	Pass					
Seeding	Pass					
		Culverts	Pass			
Sediment Traps	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT