

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

04/24/2017

Submitted Date:

05/02/2017

Document Number:

666803139**FIELD INSPECTION FORM**
 Loc ID 334755 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**17 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271951	WELL	PR	08/25/2004	GW	045-09985	ROSE RANCH 22-2A (A22W)	PR
271952	WELL	PR	01/27/2006	GW	045-09986	ROSE RANCH 22-1A (A22W)	PR
271953	WELL	PR	09/06/2004	GW	045-09987	ROSE RANCH 23-4A (A22W)	PR
272354	WELL	PR	09/02/2004	GW	045-10059	ROSE RANCH 23-6B (A22W)	PR
419695	WELL	PR	10/10/2011	GW	045-20008	ROSE RANCH 23-4D (A22W)	PR
419696	WELL	PR	10/10/2011	GW	045-20009	ROSE RANCH 23-6B1 (A22W)	PR
419698	WELL	PR	10/10/2011	GW	045-20010	ROSE RANCH 22-9B1 (A22W)	PR
419703	WELL	PR	10/10/2011	GW	045-20014	ROSE RANCH 22-9B2 (A22W)	PR
419704	WELL	PR	10/10/2011	GW	045-20015	ROSE RANCH 22-1D (A22W)	PR
419706	WELL	PR	10/10/2011	GW	045-20016	ROSE RANCH 22-8C1 (A22W)	PR
419761	WELL	PR	10/10/2011	GW	045-20018	ROSE RANCH 22-8A1 (A22W)	PR
419763	WELL	PR	10/10/2011	GW	045-20019	ROSE RANCH 22-8B (A22W)	PR
419765	WELL	PR	10/10/2011	GW	045-20021	ROSE RANCH 23-12A1	PR
419769	WELL	PR	10/10/2011	GW	045-20022	ROSE RANCH 23-6C1 (A22W)	PR

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Pig Station

# 1

Comment:

Corrective Action:

Date:

Type: Emission Control Device

# 1

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

# 1

Comment:

Corrective Action:

Date:

Type: Vertical Heated Separator

# 14

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

# 4

Comment: [Chemical units at wellhead](#)

Corrective Action:

Date:

Type: Plunger Lift

# 14

Comment:

Corrective Action:

Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment: <a href="#">With condensate tanks</a>					
Corrective Action:					Date:

**Paint**

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS	
METHANOL	1	OTHER	STEEL AST		,	
Comment:				at separators		
Corrective Action:				Date:		
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						500gal
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Comment:						
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	6	500 BBLs	STEEL AST		39.436375,-107.752410	
Comment:						
Corrective Action:				Date:		
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Comment:						
Corrective Action:				Date:		
<u>Venting:</u>						
Yes/No	NO					
Comment:						
Corrective Action:				Date:		
<u>Flaring:</u>						
Type						

Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	271951	Type:	WELL	API Number:	045-09985	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	271952	Type:	WELL	API Number:	045-09986	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	271953	Type:	WELL	API Number:	045-09987	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	272354	Type:	WELL	API Number:	045-10059	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	419695	Type:	WELL	API Number:	045-20008	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	419696	Type:	WELL	API Number:	045-20009	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	419698	Type:	WELL	API Number:	045-20010	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	419703	Type:	WELL	API Number:	045-20014	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			

Facility ID:	419704	Type:	WELL	API Number:	045-20015	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**Comment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID:	419706	Type:	WELL	API Number:	045-20016	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**Comment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID:	419761	Type:	WELL	API Number:	045-20018	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**Comment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID:	419763	Type:	WELL	API Number:	045-20019	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**Comment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID:	419765	Type:	WELL	API Number:	045-20021	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**Comment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID:	419769	Type:	WELL	API Number:	045-20022	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**Comment: [Plunger lift](#)

Corrective Action:

Date:

Environmental	
<b>Spill/Remediation:</b>	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): YES	
Comment:	
Pilot: ON	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Waddles	Pass					
Berms	Pass					
Gravel	Pass					
		Gravel	Pass			
Sediment Traps	Pass					
		Ditches	Pass			
Seeding	Pass					

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT