

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/25/2017

Submitted Date:

05/02/2017

Document Number:

666803141

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
335132 _____ Murray, Richard _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

19 Number of Comments

0 Number of Corrective Actions

 Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		COGCCInspectionReports@terraep.com	Field Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285851	WELL	PR	04/24/2007	GW	045-12575	CLOUGH RWF 522-23	PR
285852	WELL	PR	09/30/2008	GW	045-12574	CLOUGH RWF 412-23	PR
285853	WELL	PR	09/30/2008	GW	045-12573	CLOUGH RWF 422-23	PR
285854	WELL	PR	04/24/2007	GW	045-12572	CLOUGH RWF 11-23	PR
285855	WELL	PR	08/31/2008	GW	045-12571	CLOUGH RWF 22-23	PR
285856	WELL	PR	08/31/2008	GW	045-12570	CLOUGH RWF 411-23	PR
285857	WELL	PR	10/31/2008	GW	045-12569	CLOUGH RWF 312-23	PR
285858	WELL	PR	04/24/2007	GW	045-12568	CLOUGH RWF 21-23	PR
285859	WELL	PR	04/24/2007	GW	045-12567	CLOUGH RWF 321-23	PR
285860	WELL	PR	04/24/2007	GW	045-12566	CLOUGH RWF 421-23	PR
285861	WELL	PR	09/30/2008	GW	045-12565	CLOUGH RWF 512-23	PR
285862	WELL	PR	09/30/2008	GW	045-12564	CLOUGH RWF 12-23	PR
285863	WELL	PR	06/15/2008	GW	045-12563	CLOUGH RWF 311-23	PR
294707	WELL	PR	08/12/2008	GW	045-15575	CLOUGH RWF 544-15	PR
294708	WELL	PR	02/26/2008	GW	045-15576	CLOUGH RWF 156-15	PR

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type				corrective date
Horizontal Heated Separator	# 15			
Comment:				
Corrective Action:				Date:
Emission Control Device	# 0			
Comment:				
Corrective Action:				Date:
Plunger Lift	# 15			
Comment:				
Corrective Action:				Date:
Gas Meter Run	# 0			
Comment:				
Corrective Action:				Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		,
Comment:	Centralized battery				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	200 BBLs	STEEL AST		
Comment:		Centralized battery			
Corrective Action:					Date:
<u>Paint</u>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					Date:
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		
Comment:		Centralized battery			
Corrective Action:					Date:
<u>Paint</u>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					Date:
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	200 BBLs	STEEL AST		39.516348,-107.863029
Comment:					
Corrective Action:					Date:
<u>Paint</u>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate	

Comment:		
Corrective Action:		Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	285851	Type:	WELL	API Number:	045-12575	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	285852	Type:	WELL	API Number:	045-12574	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	285853	Type:	WELL	API Number:	045-12573	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	285854	Type:	WELL	API Number:	045-12572	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	285855	Type:	WELL	API Number:	045-12571	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	285856	Type:	WELL	API Number:	045-12570	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	285857	Type:	WELL	API Number:	045-12569	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	285858	Type:	WELL	API Number:	045-12568	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				

Facility ID: 285859	Type: WELL	API Number: 045-12567	Status: PR	Insp. Status: PR
Producing Well				
Comment: Plunger lift				
Corrective Action:				Date:
Facility ID: 285860	Type: WELL	API Number: 045-12566	Status: PR	Insp. Status: PR
Producing Well				
Comment: Plunger lift				
Corrective Action:				Date:
Facility ID: 285861	Type: WELL	API Number: 045-12565	Status: PR	Insp. Status: PR
Producing Well				
Comment: Plunger lift				
Corrective Action:				Date:
Facility ID: 285862	Type: WELL	API Number: 045-12564	Status: PR	Insp. Status: PR
Producing Well				
Comment: Plunger lift				
Corrective Action:				Date:
Facility ID: 285863	Type: WELL	API Number: 045-12563	Status: PR	Insp. Status: PR
Producing Well				
Comment: Plunger lift				
Corrective Action:				Date:
Facility ID: 294707	Type: WELL	API Number: 045-15575	Status: PR	Insp. Status: PR
Producing Well				
Comment: Plunger lift				
Corrective Action:				Date:
Facility ID: 294708	Type: WELL	API Number: 045-15576	Status: PR	Insp. Status: PR
Producing Well				
Comment: Plunger lift				
Corrective Action:				Date:

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): NO

Comment:

Pilot: Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Pass			
Seeding	Pass					
		Gravel	Pass			
Gravel	Pass					
		Ditches	Pass			
Ditches	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT