

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/27/2017

Submitted Date:

05/02/2017

Document Number:

666803154**FIELD INSPECTION FORM**

Loc ID 432265 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:12 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
432268	WELL	PR	02/01/2017	GW	045-21936	HMU 6-15A (J6SEB)	PR
432269	WELL	PR	05/20/2014	GW	045-21937	HMU 6-13AA (J6SEB)	PR
432272	WELL	PR	05/16/2014	GW	045-21938	HMU 6-11A (J6SEB)	PR
432277	WELL	PR	05/17/2014	GW	045-21939	HMU 6-12D (J6SEB)	PR
432280	WELL	PR	05/27/2014	GW	045-21940	HMU 6-15AA (J6SEB)	PR
432281	WELL	PR	05/14/2014	GW	045-21941	HMU 6-13A (J6SEB)	PR
432282	WELL	PR	05/17/2014	GW	045-21942	HMU 6-12DD (J6SEB)	PR
432283	WELL	PR	05/12/2014	GW	045-21943	HMU 6-13D (J6SEB)	PR
432284	WELL	SI	01/01/2017	GW	045-21944	HMU 6-15D (J6SEB)	SI

General Comment:[Shared facilities with location ID 324343](#)

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Horizontal Heated Separator

1

Comment: Corrective Action: Date:

Type: Vertical Heated Separator

9

Comment: Corrective Action: Date:

Type: Ancillary equipment

3

Comment: [Chemical units at wellhead](#)Corrective Action: Date:

Type: Gas Meter Run

1

Comment: Corrective Action: Date:

Type: Plunger Lift

9

Comment: Corrective Action: Date:

Type: Emission Control Device

1

Comment: Corrective Action: Date:

Type: Pig Station

1

Comment: Corrective Action: Date: **Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,

Comment: [Centralized battery](#)Corrective Action: Date: **Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	4	500 BBLS	STEEL AST		39.387643,-107.706289	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities						
Facility ID:	432268	Type:	WELL	API Number: 045-21936	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	432269	Type:	WELL	API Number: 045-21937	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	432272	Type:	WELL	API Number: 045-21938	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	432277	Type:	WELL	API Number: 045-21939	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	432280	Type:	WELL	API Number: 045-21940	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	432281	Type:	WELL	API Number: 045-21941	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	432282	Type:	WELL	API Number: 045-21942	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	432283	Type:	WELL	API Number: 045-21943	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Plunger lift					
Corrective Action:						Date:

Facility ID: 432284 Type: WELL API Number: 045-21944 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: Last posted production numbers Feb 2017

Corrective Action: _____ Date: _____

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON

Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
Berms	Pass					
		Ditches	Pass			
Retention Ponds	Pass					
Gravel	Pass					
		Culverts	Pass			
Rip Rap	Pass					

Comment:

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT