

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/28/2017

Submitted Date:

05/02/2017

Document Number:

668005398**FIELD INSPECTION FORM**
 Loc ID 333928 Inspector Name: DURAN, JOHN On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 100264Name of Operator: XTO ENERGY INCAddress: PO BOX 6501City: ENGLEWOOD State: CO Zip: 80155**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Trujillo, Irwin	719-846-0272/719-859-2264	irwin_trujillo@xtoenergy.com	Sr. Env. Tech., Raton Basin
Fitzgerald, Edie	719-845-2108/719-859-1394	Edie_Fitzgerald@xtoenergy.com	Env. Tech, Raton Basin
Harrison, Lyndon	505-333-3100	Lyndon_Harrison@xtoenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
272460	WELL	TA	08/15/2013	GW	071-08078	HILL RANCH 32-06	TA
275202	WELL	PR	12/24/2005	GW	071-08278	HILL RANCH 32-06CH	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 7		
Comment:			
Corrective Action:		Date:	
Type: Progressive Cavity	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment: Wellhead			
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 272460 Type: WELL API Number: 071-08078 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: Passed MiT on (5/21/12).Corrective Action: Must perform and Pass MiT. Date: 05/31/2017Facility ID: 275202 Type: WELL API Number: 071-08278 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NO

Pit ID:

Lat:

Long:

Reference Point: _____

Other: _____

Length: _____

Width: _____

Lining:

Liner Type:

Liner Condition:

Comment:

Corrective Action

Date: c**Fencing:**

Fencing Type:

Fencing Condition:

Comment:

Corrective Action

Date:

Netting:

Netting Type:

Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:

Oil Accumulation: NO2+ feet Freeboard: YESComment: 30' x 60'

Corrective Action

Date:

Permit:	Facility ID	Permit Num	Expiration Date
	292528	2059041	

Monitoring:

Monitoring Type

Comment`

Other

blue stake

COGCC Comments

Comment	User	Date
<u>Passed MiT on (05/21/12). Need to perform and pass MiT on or before (05/31/17).</u>	duranj	04/28/2017