

Location

Lease Road:			
Type	Access		
comment:	Trail through CRP		
Corrective Action:		Date:	

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign mounted to fence		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Lease sign for associated wells mounted to meter shed		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date:	<input style="width: 80%;" type="text"/>

Overall Good:

Spills:			
Type	Area	Volume	

In Containment:	No
Comment:	<input style="width: 95%;" type="text"/>
<input type="checkbox"/>	Multipple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Metal panels around wellhead, VGS and meter shed		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Vertical Separator	# 2		
Comment:	2-Vertical gas separators 50% buried by meter shed		
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:	Shared meter run for Chase G 6-28 and Strangways 7-21		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			

Comment:		
Corrective Action:	Date:	

Inspected Facilities

Facility ID: 254117 Type: WELL API Number: 125-07995 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Casing production. Central meter run for \(Chase G. 6-28 & Strangways 7-21\)](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Compaction	Pass			

Comment: Location and access are grassed over

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT