

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/28/2017

Submitted Date:

05/01/2017

Document Number:

674703876**FIELD INSPECTION FORM**
 Loc ID 335798 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:16 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Janicek, Jake		JJanicek@caerusoilandgas.com	
McKee, Michael		MMckee@caerusoilandgas.com	
Elsener, Garrett		garrett@caerusoilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
265451	WELL	PR	07/31/2009	GW	045-09020	CHEVRON 22-7D	PR
265452	WELL	PR	08/31/2009	GW	045-09019	CHEVRON 23-7D	PR
265453	WELL	SI	01/01/2017	GW	045-09016	CHEVRON 12-7D	SI
265454	WELL	SI	01/01/2017	GW	045-09018	CHEVRON 13-7D	SI
265455	WELL	PR	03/31/2010	GW	045-09017	CHEVRON 14-7D	PR
265456	WELL	PR	03/31/2010	GW	045-09021	CHEVRON 24-7D	PR
291053	WELL	PR	08/01/2010	GW	045-14269	CHEVRON-MARATHON 12C-7D	PR
291054	WELL	PR	09/01/2010	GW	045-14270	Chevron 12D-7D	PR
291055	WELL	PR	08/01/2009	GW	045-14271	CHEVRON 13A-7D	PR
291056	WELL	PR	03/31/2011	GW	045-14272	Chevron 13C-7D	PR
291057	WELL	PR	09/01/2010	GW	045-14273	Chevron 13D-7D	PR
291058	WELL	PR	09/01/2010	GW	045-14274	Chevron 14A-7D	PR
291059	WELL	PR	10/01/2011	GW	045-14275	CHEVRON 23D-7D	PR
291060	WELL	PR	10/01/2011	GW	045-14276	Chevron 12A-7D	PR
291061	WELL	PR	10/01/2011	GW	045-14277	Chevron 11D-7D	PR
291075	WELL	PR	09/01/2010	GW	045-14291	Chevron 24B-7D	PR
291076	WELL	PR	03/31/2011	GW	045-14292	Chevron 24A-7D	PR

General Comment:

Location

Lease Road:			
Type	Main		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 866-580-9382

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:				corrective date
Type: Pig Station	# 17			
Comment:				
Corrective Action:				Date:
Type: Plunger Lift	# 17			
Comment:				
Corrective Action:				Date:
Type: Bird Protectors	# 9			
Comment:				
Corrective Action:				Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 265451	Type: WELL	API Number: 045-09020	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:		Date:		
Facility ID: 265452	Type: WELL	API Number: 045-09019	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:		Date:		
Facility ID: 265453	Type: WELL	API Number: 045-09016	Status: SI	Insp. Status: SI
Idle Well				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____				
Comment:				
Corrective Action:		Date:		
Facility ID: 265454	Type: WELL	API Number: 045-09018	Status: SI	Insp. Status: SI
Idle Well				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____				
Comment:				
Corrective Action:		Date:		
Facility ID: 265455	Type: WELL	API Number: 045-09017	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:		Date:		
Facility ID: 265456	Type: WELL	API Number: 045-09021	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:		Date:		
Facility ID: 291053	Type: WELL	API Number: 045-14269	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:		Date:		
Facility ID: 291054	Type: WELL	API Number: 045-14270	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:		Date:		

<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 291055 Type: WELL API Number: 045-14271 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 291056 Type: WELL API Number: 045-14272 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 291057 Type: WELL API Number: 045-14273 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 291058 Type: WELL API Number: 045-14274 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 291059 Type: WELL API Number: 045-14275 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 291060 Type: WELL API Number: 045-14276 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 291061 Type: WELL API Number: 045-14277 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 291075 Type: WELL API Number: 045-14291 Status: PR Insp. Status: PR				

Producing Well			
Comment:	Producing well		
Corrective Action:		Date:	
Facility ID:	291076	Type:	WELL
API Number:	045-14292	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:	Producing well		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction	Pass			
		Ditches	Pass			
Compaction	Pass					
Seeding	Pass					
		Culverts	Pass			
		Gravel	Pass			
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401270752	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4135979
674703881	Location photo CHEVRON 12-7D	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4135975