

## DWD-1 Corrective Actions Completed April 12, 2017



Photo 1: Repaired erosion on well pad/gravel area. Installed rip-rap rundown on slope for additional stabilization.



DWD-1 Weed Spray Completed 5/3/17



Weed wilt after treatment completed on  
5/3/17