

Final Reclamation Inspection

April 27, 2017

Operator: SLAWSON EXPLORATION COMPANY INC- #10334

API: 05-123-31983

Weld County, CO

SESE Section 12 T11N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Boxcar #12-11-67
API: 05-123-31983



Photo 1. Photo taken from the approximate center of location, facing West. No evidence of disturbance at location, confirming the location was never constructed.



Photo 2. Photo taken from the approximate center of location, facing North. No evidence of disturbance at location, confirming the location was never constructed.

Inspection Photos
Location Name: Boxcar #12-11-67
API: 05-123-31983



Photo 3. Photo taken from the approximate center of location, facing East. No evidence of disturbance at location, confirming the location was never constructed.



Photo 4. Photo taken from the approximate center of location, facing South. No evidence of disturbance at location, confirming the location was never constructed.