

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/04/2017

Submitted Date:

05/08/2017

Document Number:

680301943**FIELD INSPECTION FORM**

Loc ID 312138 Inspector Name: SCHURE, KYM On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10548Name of Operator: HRM RESOURCES II LLCAddress: 410 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Pape, Terry	970-768-5700	tpape@hrmres.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
218713	WELL	PR	04/26/2007	OW	075-05445	FRASCO 1-B	PA

**General Comment:**

[P&A Pumping top plug @ 253'. WOC next day for tag and finish to surface. No problems indicated.](#)

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Other	# 0		corrective date
Comment:	Equipment remains on-site, upon P&A completion remove all equipment from location		
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 218713 Type: WELL API Number: 075-05445 Status: PR Insp. Status: PA**Cement**Cement ContractorContractor Name: RangerContractor Phone: 713-935-8900Surface CasingCement Volume (sx): 40+100Circulate to Surface:           Cement Fall Back:           Top Job, 1" Volume:           Intermediate CasingCement Volume (sxs):           Good Return During Job:           Production CasingCement Volume (sx): 2+50Good Return During Job: YESPlugging OperationsDepth Plugs(feet range): 5449,4487,1400,253Cement Volume (sx): 2+50+40+100Good Return During Job: YESCement Type: 15.8#

Comment: Setting top/surface plug @ 253' w/100 sks of 15.8# cement. WOC for next day tag and top off. No problems indicated.

Corrective Action: Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	In Process	Other	In Process			

Comment: Continue stormwater erosion BMP's until final reclamation is approved.

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT