

Photo#1:
View North over Location Center



Photo#2:
View South over Location Center



May 3, 2017

Photo#3:
View East over Location Center



Photo#4:
View West over Location Center



May 3,2017

Photo#3:

Close up of Vegetation Disturbed Area



Photo#4:

Close up of Vegetation Reference area



May 3,2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Black Hills PA API# 077-08369