

# Final Reclamation and Stormwater Inspection

April 27, 2017

Operator: SLAWSON EXPLORATION COMPANY INC- #10334

API: 05-123-31793

Weld County, CO

NWNW Section 24 T11N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: BUSHWACKER #24-11-67  
API: 05-123-31793



**Photo 1.** Photo taken from the approximate center of location, facing West. No evidence of wellbore at location. Vegetative growth appears reflective of reference areas with the addition of a bunch grass that was used in the seed mix.



**Photo 2.** Photo taken from the approximate center of location, facing North. No evidence of wellbore at location. Vegetative growth appears reflective of reference areas with the addition of a bunch grass that was used in the seed mix.

Inspection Photos  
Location Name: BUSHWACKER #24-11-67  
API: 05-123-31793



**Photo 3.** Photo taken from the approximate center of location, facing East. No evidence of wellbore at location. Vegetative growth appears reflective of reference areas with the addition of a bunch grass that was used in the seed mix.



**Photo 4.** Photo taken from the approximate center of location, facing South. No evidence of wellbore at location. Vegetative growth appears reflective of reference areas with the addition of a bunch grass that was used in the seed mix.



Inspection Photos  
Location Name: BUSHWACKER #24-11-67  
API: 05-123-31793



**Photo 5.** Photo taken from the approximate entrance to location, facing East. Vegetative growth appears reflective of reference areas with the addition of a bunch grass that was used in the seed mix.



**Photo 6.** Photo taken a portion of the access road, facing South. Vegetative growth appears reflective of reference areas with the addition of a bunch grass that was used in the seed mix.