

Final Reclamation and Stormwater Inspection

April 27, 2017

Operator: SLAWSON EXPLORATION COMPANY INC- #10334

API: 05-123-32459

Weld County, CO

NWNW Section 6 T11N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Quickdraw #6-11-66
API: 05-123-32459



Photo 1. Photo taken from the approximate center of location, facing West. No evidence of wellbore or disturbance at location.



Photo 2. Photo taken from the approximate center of location, facing North. No evidence of wellbore or disturbance at location.

Inspection Photos
Location Name: Quickdraw #6-11-66
API: 05-123-32459



Photo 3. Photo taken from the approximate center of location, facing East. No evidence of wellbore or disturbance at location.



Photo 4. Photo taken from the approximate center of location, facing South. No evidence of wellbore or disturbance at location.

Inspection Photos
Location Name: Quickdraw #6-11-66
API: 05-123-32459



Photo 5. Close-up photo taken from the approximate center of location. No evidence of wellbore or disturbance at location. Location appears reflective of reference area conditions.



Photo 6. Reference photo taken north of location, facing West. Location appears reflective of reference area conditions.