



photo 1: Facing northwest along the access road.



photo 2: Facing back toward the southeast along the access road.



photo 3: Facing toward the east side of the location.



photo 4: Facing northwest toward the location. Areas of the location were seeded and straw mulched.