

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/05/2017

Submitted Date:

05/05/2017

Document Number:

674200055**FIELD INSPECTION FORM**

Loc ID 336382 Inspector Name: Gomez, Jason On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10633Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLCAddress: 1801 CALIFORNIA STREET #2500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:15 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Adamczyk, Megan		megan.adamczyk@state.co.us	
,		cogcc.inspections@crestonepr.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271268	WELL	PR	06/22/2010	GW	123-22015	WOOLLEY 21-7	SI
284163	WELL	PR	08/11/2006	OW	123-23758	BILLINGS 21-7	SI
421621	WELL	PR	09/05/2012	GW	123-32979	WOOLLEY 11-7	SI
421629	WELL	PR	11/05/2012	OW	123-32982	WOOLLEY 22-7	SI
421632	WELL	PR	10/10/2012	OW	123-32984	WOOLLEY 2-4-7	SI
421635	WELL	PR	11/02/2012	OW	123-32986	WOOLLEY 4-0-7	SI

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Ancillary equipment

#

Comment: APPROX 32' SOUNDS WALLS ON NORTH SIDE OF LOCATION BEING INSTALLED

Corrective Action:

Date:

Type: Ancillary equipment

#

Comment: MISCELLANEOUS FRAC EQUIPMENT ON LOCATION

Corrective Action:

Date:

Venting:

Yes/No

NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 271268 Type: WELL API Number: 123-22015 Status: PR Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: EQUIPMENT ONSITE

Comment: SI FOR FRACK

Corrective Action:

Date:

BradenHead

Comment: PLUMBED TO SURFACE

Corrective Action:

Date:

Facility ID: 284163 Type: WELL API Number: 123-23758 Status: PR Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: EQUIPMENT ONSITE

Comment: SI FOR FRACK

Corrective Action:

Date:

BradenHead

Comment: PLUMBED TO SURFACE

Corrective Action:

Date:

Facility ID: 421621 Type: WELL API Number: 123-32979 Status: PR Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: EQUIPMENT ONSITE

Comment: SI FOR FRACK

Corrective Action:

Date:

BradenHead

Comment: PLUMBED TO SURFACE

Corrective Action:

Date:

Facility ID: 421629 Type: WELL API Number: 123-32982 Status: PR Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: EQUIPMENT ONSITE

Comment: SI FOR FRACK

Corrective Action:

Date:

BradenHead

Comment: PLUMBED TO SURFACE

Corrective Action:

Date:

Facility ID: 421632 Type: WELL API Number: 123-32984 Status: PR Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: EQUIPMENT ONSITE

Comment: SI FOR FRACK

Corrective Action:

Date:

BradenHead

Comment: PLUMBED TO SURFACE

Corrective Action:

Date:

Facility ID: 421635 Type: WELL API Number: 123-32986 Status: PR Insp. Status: SI

Complaint

Comment: Complaint Received May 5 2017

Field Inspector Assigned: Jason E. Gomez

Complaint Received:

Date: 5-5-2017 Time 1000 Hrs

Contacted by Complaint Specialist per Complaint Response forms

Date: 5-5-2017

Well Number#: Location #: 336382

Inspection Document #: 674200055

Nature of complaint: Noise

Field Inspector Actions:

On 5-5-2017, I was contacted by complaint specialist Megan Adamczyk in reference to several complaints received by the COGCC about noise occurring in the Erie are of CR 10.5 and WCR 3.

On 5-5-2017, I performed a complete site inspection of the location located approx. 1/4 mile north of 3 WCR. At the time of inspection, I observed a frac pad where Crestone Peak was conducting remote frac operations on the Woolley Becky Sosa location and the Crestone Peak Hilltop locations. I reviewed location records, which did not show any abnormal fracking conditions at the time of the complaints. I also reviewed Environmental Noise Control Inc. continuous sound study information which also did not show any exceedance of COGCC rules at the times of the complaints.

I performed a sound study located approx. 350' to the south of the noise source per COGCC guidance. This study along with any other supporting documentation is attached to the above mentioned site inspection report.

All information reviewed and site inspection information were submitted to the complaint specialist for further review.

No violations of COGCC rules were observed at the time of the inspection.

Corrective Action:

Date:

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: EQUIPMENT ONSITE

Comment: SI FOR FRACK

Corrective Action:

Date:

BradenHead	
Comment:	PLUMBED TO SURFACE
Corrective Action:	
	Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
Ditches	Pass			Covering Materials	Pass	
Berms	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	
Gravel	Pass					
Retention Ponds	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674200056	SOUND STUDY RESULTS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4142455
674200058	Photo of sound study location	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4142456