

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/08/2017

Submitted Date:

05/10/2017

Document Number:

668005417

**FIELD INSPECTION FORM**

Loc ID 309118 Inspector Name: DURAN, JOHN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 100264  
Name of Operator: XTO ENERGY INC  
Address: PO BOX 6501  
City: ENGLEWOOD State: CO Zip: 80155

**Findings:**

6 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Trujillo, Irwin	719-846-0272/719-859-2264	irwin_trujillo@xtoenergy.com	Sr. Env. Tech., Raton Basin
Harrison, Lyndon	505-333-3100	Lyndon_Harrison@xtoenergy.com	
Fitzgerald, Edie	719-845-2108/719-859-1394	Edie_Fitzgerald@xtoenergy.com	Env. Tech, Raton Basin

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288303	WELL	PR	10/31/2007	GW	071-09107	GOLDEN EAGLE 32-8	PR

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No  
 Comment:

Multiple Spills and Releases?

**Equipment:**

Type	#		corrective date
Type: Deadman # & Marked	# 5		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Progressive Cavity	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLS	STEEL AST		,
Comment:	1 - 25 bbl ST				
Corrective Action:				Date:	

<b>Paint</b>				
Condition				
Other (Content)				
Other (Capacity)				
Other (Type)				
<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:
<b>Venting:</b>				
Yes/No				
Comment:				
Corrective Action:				Date:
<b>Flaring:</b>				
Type				
Comment:				
Corrective Action:				Date:

**Inspected Facilities**

Facility ID: 288303 Type: WELL API Number: 071-09107 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Type: Produced Water      Lined: NO      Pit ID:      Lat:      Long:

Reference Point: \_\_\_\_\_      Other: \_\_\_\_\_      Length: \_\_\_\_\_      Width: \_\_\_\_\_

**Lining:**

Liner Type:      Liner Condition:

Comment:

Corrective Action

Date: c

**Fencing:**

Fencing Type:      Fencing Condition:

Comment:

Corrective Action

Date:

**Netting:**

Netting Type:      Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:      Oil Accumulation: NO      2+ feet Freeboard: YES

Comment: 30' x 60'

Corrective Action

Date:

Permit:	Facility ID	Permit Num	Expiration Date
	292678	2059191	

Monitoring:	Monitoring Type	Comment`
	Other	Blue stake