

## Rangely surface clean up – RWSU Magor1

Magor 1 (GPS 40.1448n, 108.9164w)

Restoration:

1. A 100ft radius around the well marker was cleaned. All miscellaneous debris and trash was properly disposed.
2. The entire concrete cellar and pad was exposed and removed.
3. The excavation was backfilled with clean import soil.
4. The electrical power box was removed with cable.

Concrete area





## Rangely surface clean up – RWSU Magor1

Before



Before





## Rangely surface clean up – RWSU Magor1






## Rangely surface clean up – RWSU Magor1



Anchors



Electrical Box





## Rangely surface clean up – RWSU Magor1



- All concrete was hauled off.
- All trash was properly disposed
- All was metal NORM (no issues) and placed in the metal bin.
- No BMP needed.