

Construction and Stormwater Inspection

May 5, 2017

Operator: VERDAD RESOURCES LLC- #10651

Location ID: 450069

Weld County, CO

NWSE Section 34 T1N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: HOMESTEAD PAD /1N66W34

Location ID: 450069



Photo 1. Photo taken from the northeast location, facing South. A ditch and berm BMP has been installed around the entire perimeter of the location.



Photo 2. Photo taken from the northeast location, facing West. A ditch and berm BMP has been installed around the entire perimeter of the location.

Inspection Photos

Location Name: HOMESTEAD PAD /1N66W34

Location ID: 450069



Photo 3. Photo taken from the northern location, facing West. A ditch and berm BMP has been installed around the entire perimeter of the location.



Photo 4. Photo taken from the northwestern location, facing West. Topsoil has been salvaged and stored along the western perimeter of the location.

Inspection Photos

Location Name: HOMESTEAD PAD /1N66W34

Location ID: 450069



Photo 5. Photo taken from the western location, facing South. A ditch and berm BMP has been installed around the entire perimeter of the location.



Photo 6. Photo taken from the southwestern location, facing East. A ditch and berm BMP has been installed around the entire perimeter of the location.

Inspection Photos
Location Name: HOMESTEAD PAD /1N66W34
Location ID: 450069



Photo 7. Photo taken from the southern location, facing East. A ditch and berm BMP has been installed around the entire perimeter of the location.



Photo 8. Photo taken from the southeastern location, facing North. A ditch and berm BMP has been installed around the entire perimeter of the location.