



**photo 1:** Facing toward the access road of the location.



**photo 2:** Facing southwest toward the location.





**photo 3:** North side of the location facing southwest.



**photo 4:** Facing east along the north fill slope.





**photo 5:** Facing southwest toward the cut slope of the location.



**photo 6:** There are signs of erosion occurring at the southwest corner of the pad which is depositing sediment to this area.





**photo 7:** Southeast side of the location facing west. The red arrow points to where noxious weeds are located in photo below.



**photo 8:** There is Canada thistle and Common mullein growing in rock rip rap at south side of the location.