

May 10, 2017 COGCC Environmental Inspection of Think Oil Inc Vaughn #1 Location ID: 391537, API 081-05332



One of two spoil pile alleged E&P impacted material

approximately 8'x6'x4'.



One of two spoil pile alleged E&P impacted material

approximately 8'x6'x4'.



Two of two spoil piles alleged E&P impacted material

approximately 8'x6'x4'.





approximately 8'x6'x4'.

Two of two spoil piles alleged E&P impacted material



pad around well. No visible staining or oil leaks noted.

P&Aed Vauhn #1, API 081-05332 well with absorbent



absorbent pads and soil.

Approximate 48-inch by 24 inch container with oily



fresh water was dumped during the PA activities.

Approximate 20 feet in length depression where



View looking north west. Note the two spoil piles.