

# Construction and Stormwater Inspection

May 5, 2017

Operator: KERR MCGEE OIL & GAS ONSHORE LP- #47120

Location ID: 443598

Weld County, CO

NWNE Section 8 T1N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: GABEL /37N-8HZ  
Location ID: 443598



**Photo 1.** Photo taken from the southwestern location, facing North. A ditch and berm BMP has been installed around the perimeter of the location.



**Photo 2.** Photo taken from the northwest location, facing Southeast. A sediment trap has been installed with outlet protection devices.

Inspection Photos  
Location Name: GABEL /37N-8HZ  
Location ID: 443598



**Photo 3.** Photo taken from the sediment trap, facing East. Erosion is occurring at the inlet of the sediment trap because there is no inlet protection. May need to install inlet protection and monitor to ensure erosion does not progress further.



**Photo 4.** Photo taken from the northern location, facing East. A ditch and berm BMP has been installed around the perimeter of the location.



Inspection Photos  
Location Name: GABEL /37N-8HZ  
Location ID: 443598



**Photo 5.** Photo taken from the northeastern location, facing Southeast. A ditch and berm BMP has been installed around the perimeter of the location but stops short along the northeastern location.