

FORM  
INSPRev  
X/15

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/03/2017

Submitted Date:

05/15/2017

Document Number:

680301925**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
312325 \_\_\_\_\_ SCHURE, KYM \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 11001  
 Name of Operator: BROWN OIL & GAS LLC  
 Address: 10481 COUNTY ROAD 20.5  
 City: STERLING State: CO Zip: 80751

**Findings:**

8 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

| Contact Name | Phone        | Email                         | Comment |
|--------------|--------------|-------------------------------|---------|
| Brown, Mark  | 970-522-1072 | brown_oil_and_gas@hotmail.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name    | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 278861      | WELL | PR     | 02/28/2008  | GW         | 075-09346 | JULIE CAMPBELL 1 | SI          |

**General Comment:**

[Routine Site Inspection FIR](#)

**Location**

**Lease Road:**

|                    |              |  |       |
|--------------------|--------------|--|-------|
|                    | Type Access  |  |       |
| comment:           | Satisfactory |  |       |
| Corrective ActionL |              |  | Date: |

Overall Good:

**Signs/Marker:**

|                    |               |  |       |
|--------------------|---------------|--|-------|
|                    | Type WELLHEAD |  |       |
| Comment:           | Satisfactory  |  |       |
| Corrective Action: |               |  | Date: |

Emergency Contact Number:

|                    |              |  |             |
|--------------------|--------------|--|-------------|
| Comment:           | Satisfactory |  |             |
| Corrective Action: |              |  | Date: _____ |

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |  |
|------|------|--------|--|--|--|
|      |      |        |  |  |  |

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

**Equipment:**

|                                 |     |  |  | corrective date |
|---------------------------------|-----|--|--|-----------------|
| Type: Vertical Heated Separator | # 1 |  |  |                 |
| Comment:                        |     |  |  |                 |
| Corrective Action:              |     |  |  | Date:           |
| Type: Gas Meter Run             | # 1 |  |  |                 |
| Comment:                        |     |  |  |                 |
| Corrective Action:              |     |  |  | Date:           |
| Type: Pump Jack                 | # 1 |  |  |                 |
| Comment:                        |     |  |  |                 |
| Corrective Action:              |     |  |  | Date:           |
| Type: Vertical Separator        | # 2 |  |  |                 |
| Comment:                        |     |  |  |                 |
| Corrective Action:              |     |  |  | Date:           |
| Type: Bird Protectors           | # 1 |  |  |                 |
| Comment:                        |     |  |  |                 |
| Corrective Action:              |     |  |  | Date:           |

**Tanks and Berms:**

| Contents  | #            | Capacity | Type      | Tank ID | SE GPS                |
|-----------|--------------|----------|-----------|---------|-----------------------|
| CRUDE OIL | 2            | 300 BBLs | STEEL AST |         | 40.938912,-103.422211 |
| Comment:  | Satisfactory |          |           |         |                       |

|                    |       |
|--------------------|-------|
| Corrective Action: | Date: |
|--------------------|-------|

**Paint**

|                  |  |  |
|------------------|--|--|
| Condition        |  |  |
| Other (Content)  |  |  |
| Other (Capacity) |  |  |
| Other (Type)     |  |  |

**Berms**

| Type   | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |       |
|--|----------|---------------------|---------------------|-------------|-------|
| Earth  | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |       |
| Comment: <span style="color:blue;">Satisfactory</span> |          |                     |                     |             |       |
| Corrective Action:                                     |          |                     |                     |             | Date: |

**Venting:**

|                    |  |       |
|--------------------|--|-------|
| Yes/No             |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**

Facility ID: 278861 Type: WELL API Number: 075-09346 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Other            | In Process      | Other                   | In Process            |               |                          |         |

Comment: [Use BMP's for stormwater erosion management](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

| Permit: | Facility ID | Permit Num | Expiration Date |
|---------|-------------|------------|-----------------|
|         | 295337      | 1981728    |                 |
|         | 425838      | 1642067    |                 |
|         | 295338      | 1981729    |                 |
|         | 294277      | 1981022    |                 |