

Inspection Photos
Location Name: Arapaho State 6-81-36-3
API: 05-057-06507



Photo 1. View at entrance to location facing east. No interim reclamation apparent.

Inspection Photos
Location Name: Arapaho State 6-81-36-3
API: 05-057-06507



**Photo 2. Unconsolidated, pervious berm in foreground.
Unprotected topsoil pile in background.**



Photo 3. No wildlife protection apparent on exhaust.