

Inspection Photos
Location Name: State 1-15
API: 05-107-06033



Photo 1. View at entrance to location facing southeast.

Inspection Photos
Location Name: State 1-15
API: 05-057-06033



Photo 2. Noxious weeds on access road.



Photo 3. Noxious weeds immediately adjacent to access road.