

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/12/2017

Submitted Date:

05/16/2017

Document Number:

666803173**FIELD INSPECTION FORM**

Loc ID 335038 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1400City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
, Laramie		cogccnotifications@laramie-energy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
298566	WELL	PR	03/03/2011	GW	045-17256	HONEA 19-05B	PR
298567	WELL	PR	03/03/2011	GW	045-17257	HONEA 24-01C	PR
419429	WELL	PR	03/24/2011	GW	045-19930	HONEA FED. 24-09C	PR

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Chemical unit at wellhead		
Corrective Action:			Date:
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 3		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0				,
Comment:					
Corrective Action:					Date:

**Paint**

Condition		
Other (Content)		
Other (Capacity)		

Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	3	400 BBLs	STEEL AST		39.426900,-107.822250	
Comment:						
Corrective Action:					Date:	
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	
<u>Venting:</u>						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
<u>Flaring:</u>						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities									
Facility ID:	298566	Type:	WELL	API Number:	045-17256	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	298567	Type:	WELL	API Number:	045-17257	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	419429	Type:	WELL	API Number:	045-19930	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			

Environmental	
<b>Spill/Remediation:</b>	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): YES	
Comment:	
Pilot: ON	Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Sediment Traps	Pass					
		Ditches	Pass			
		Culverts	Pass			
		Rip Rap	Pass			
		Check Dams	Pass			
		Gravel	Pass			
Ditches	Pass					
		Sediment Traps	Pass			
Gravel	Pass					
Berms	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT