

Inspection Photos
Location Name: Cody 1
API: 05-057-05135



Photo 1. Photo at entrance to location facing northeast.



Photo 2. Landfarm area with no containment.

Inspection Photos
Location Name: Cody 1
API: 05-057-05135



Photo 3. Close-up of landfarm material.



Photo 4. Close-up of landfarm material.