

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/10/2017

Submitted Date:

05/12/2017

Document Number:

677900233**FIELD INSPECTION FORM**Loc ID: 391537 Inspector Name: FISCHER, ALEX On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 87815Name of Operator: THINK OIL INCAddress: 11094 FITZHUGH RDCity: AUSTIN State: TX Zip: 78736**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Neidel, Kris		kris.neidel@state.co.us	
Andrews, Dave		david.andrews@state.co.us	
Burger, Craig		craig.burger@state.co.us	

General Comment:

On May 10, 2017 COGCC Environmental Staff (Alex Fischer and Kris Neidel) conducted an environmental field inspection of Think Oil Inc Vaughn #1 Location ID: 391537, API 081-05332.. Weather was overcast and light rain and temperature app 50s degree F. The well has been P and A. was not producing at time of inspection. For the most recent Field inspection report of this facility, please refer to document # 670201404.

The following is a summary:

- There are two spoil piles (approximately 8'x 6' x 4') of alleged E&P impacted waste.
- There is an approximate 48-inch by 24-inch container of oil soaked absorbent pads and E&P impacted soil.
- An approximate 20' long by 4' wide by 2' deep depression where fresh water as allegedly disposed of.
- Open excavation (10-diameter by 4 feet in depth) around the P&Aed Vaughn #1, API 081-05332 well.

Corrective Actions:

Remove and properly dispose of the two spoil piles, container of oily material, impacted material around the well head, and surficial soil in the depression.

Finalize the abandonment of the Vaughn #1 well.

Environmental**Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil				
Comment	<ul style="list-style-type: none"> • There are two spoil piles (approximately 8'x 6' x 4') of alleged E&P impacted waste. • There is an approximate 48-inch by 24-inch container of oil soaked absorbent pads and E&P impacted soil. • Open excavation (10-diameter by 4 feet in depth) around the P&Aed Vaughn #1, API 081-05332 well. 			
Corrective Action	<p>Remove and properly dispose of the two spoil piles, container of oily material, impacted material around the well head, and surficial soil in the depression.</p> <p>Finalize the abandonment of the Vaughn #1 well.</p>			Date: _____

Spill/Remediation:

Comment:	• An approximate 20' long by 4' wide by 2' deep depression where fresh water as allegedly disposed of.		
Corrective Action:	Remove surficial soil and properly dispose.		
			Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

COGCC Comments

Comment	User	Date
<p>On May 10, 2017 COGCC Environmental Staff (Alex Fischer and Kris Neidel) conducted an environmental field inspection of Think Oil Inc Vaughn #1 Location ID: 391537, API 081-05332.. Weather was overcast and light rain and temperature app 50s degree F. The well has been P and A. was not producing at time of inspection. For the most recent Field inspection report of this facility, please refer to document # 670201404.</p> <p>The following is a summary:</p> <ul style="list-style-type: none"> • There are two spoil piles (approximately 8'x 6' x 4') of alleged E&P impacted waste. • There is an approximate 48-inch by 24-inch container of oil soaked absorbent pads and E&P impacted soil. • An approximate 20' long by 4' wide by 2' deep depression where fresh water as allegedly disposed of. • Open excavation (10-diameter by 4 feet in depth) around the P&Aed Vaughn #1, API 081-05332 well. <p>Corrective Actions:</p> <p>Remove and properly dispose of the two spoil piles, container of oily material, impacted material around the well head, and surficial soil in the depression.</p> <p>Finalize the abandonment of the Vaughn #1 well.</p>	fischera	05/12/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401282079	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4146250
677900234	20170510 Think Oil Location ID 391537 API 08105332.pdf	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4146245

677900235	20170510 Photolog Think Oil Location ID 391537 API 08105332.pdf	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4146246
-----------	-----------------------------------------------------------------------	---------------------------------------------------------------------------------------------------------------------------------------------------------------------