

Inspection Photos

05/16/2017

Operator: Magpie Operating, Inc #52530

Location ID: 400736

Inspection Doc. Number: 682502035

Washington County, CO

Aaron Trujillo

Reclamation Specialist

COGCC



Inspection Photos
Operator: Magpie Operating, Inc #52530
Location ID: 400736



Photo 1: Photo of GPS verifying location.

Inspection Photos
Operator: Magpie Operating, Inc #52530
Location ID: 400736



Photo 2: Photo taken from the location, facing north. Photo shows vegetation over the reclamation area.



Photo 3: Photo taken from the location, facing east. Photo shows vegetation over the reclamation area.

Inspection Photos
Operator: Magpie Operating, Inc #52530
Location ID: 400736



Photo 4: Photo taken from the location, facing south. Photo shows vegetation over the reclamation area.



Photo 5: Photo taken from the location, facing west. Photo shows vegetation over the reclamation area.