

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/10/2017

Submitted Date:

05/15/2017

Document Number:

674901650

### FIELD INSPECTION FORM

Loc ID 325953 Inspector Name: Hughes, Jim On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10000  
Name of Operator: BP AMERICA PRODUCTION COMPANY  
Address: 380 AIRPORT RD  
City: DURANGO State: CO Zip: 81303

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Gintautas, Peter		peter.gintautas@state.co.us	
Chesson, Bob		robert.chesson@state.co.us	
Inspections, All		SanJuanCOGCC@bp.com	<a href="#">SW Inspection Reports</a>
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com	<a href="#">SW Inspection Reports</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215628	WELL	PR	03/21/1989	GW	067-07233	WILBOURN FEDERAL 1	EI

**General Comment:**

On May 10, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Wilbourn Federal #1. The purpose of this location inspection was to collect samples for the COGCC's statewide produced water NORM study. BP representative Jeramie Price was on site during this inspection. For the most recent field inspection report for this facility, please refer to document #680600075.

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Free standing sign near separator. Old style sign remains on location.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>		

Overall Good:

**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	Stock panel fencing surrounds well head and pump jack.		
Corrective Action:		Date:	

**Equipment:**

Type			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Telemetry		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 215628 Type: WELL API Number: 067-07233 Status: PR Insp. Status: EI

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_  
 Comment:   
 Corrective Action:  Date: \_\_\_\_\_  
 Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_  
 Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

<b>Sample</b>	Sample Type: <u>PRODUCED</u>			
Time: <u>05/10/2017 10:45</u> (MM/dd/yyyy hh:mm)	GPS: Lat <u>37.291934</u>	Long <u>-107.679939</u>		
BTEX: _____	TPH: _____	Anion: _____	Captions: _____	General Chemistry: _____
Dissolved Methane: _____	Composition: _____	Stable Isotopes: _____	8260: _____	
8270: _____	RCRA Metals: _____	910-Metals: _____	PAH: _____	
Other: <u>2017 COGCC Produced Water NORM Study</u>				
Comment: <input type="text"/>				

<b>Sample</b>	Sample Type: <u>PRODUCED</u>			
Time: <u>05/10/2017 11:00</u> (MM/dd/yyyy hh:mm)	GPS: Lat <u>37.291934</u>	Long <u>-107.679939</u>		
BTEX: _____	TPH: _____	Anion: _____	Captions: _____	General Chemistry: _____
Dissolved Methane: _____	Composition: _____	Stable Isotopes: _____	8260: _____	
8270: _____	RCRA Metals: _____	910-Metals: _____	PAH: _____	
Other: <u>2017 COGCC Produced Water NORM Study</u>				
Comment: <input type="text"/>				

**Lab:**

Lab Name   
 ALS Environmental

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Rip Rap	Pass					
Gravel	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
On May 10, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Wilbourn Federal #1. The purpose of this location inspection was to collect samples for the COGCC's statewide produced water NORM study. BP representative Jeramie Price was on site during this inspection. For the most recent field inspection report for this facility, please refer to document #680600075. One produced water sample was collected from the BP Wilbourn Federal #1 at the well head. Another produced water sample was collected from the same valve as a duplicate.	hughesj	05/15/2017

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401284035	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4147732">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4147732</a>
674901651	Wilbourn Federal #1 location photo.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4147723">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4147723</a>
674901652	1" valve that samples were collected from.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4147724">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4147724</a>
674901653	Piping configuration for sample collection.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4147725">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4147725</a>
674901654	BP representative assisting in sample collection.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4147726">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4147726</a>