

## Inspection Photos

Location Number:446137



Location entrance signage




Culvert at location entrance

## Inspection Photos

Location Number:446137



Conex chemical storage. Curtains being repaired, damaged during move.




BOP chart



# Inspection Photos

Location Number:446137



BOP test procedure



Bales ditches and signage at location entrance.