

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/16/2017

Submitted Date:

05/22/2017

Document Number:

674200072**FIELD INSPECTION FORM**

Loc ID 434375 Inspector Name: Gomez, Jason On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10633Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLCAddress: 1801 CALIFORNIA STREET #2500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		Cogcc.inspections@crestone pr.com	
Adamczyk, Megan		megan.adamczyk@state.co.u s	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
434370	WELL	DG	04/24/2017	LO	123-38122	Waste Connections 3A- 29H-M168	DG

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	Field Flare	
Comment:	Not in use at time of inspection	
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 434370 Type: WELL API Number: 123-38122 Status: DG Insp. Status: DG**Complaint**Comment: Complaint Received May 15, 2017Field Inspector Assigned: Jason E. GomezComplaint Received:Date: 5-13-2017/ 5-15-2017 Time 0900 HrsContacted by Complaint Specialist per Complaint Response formsDate: 5-16-2017Well Number#: Location #: 434375Inspection Document #: 674200072Nature of complaint: OdorField Inspector Actions:On 5-15-2017, I was contacted by complaint specialist Megan Adamczyk in reference to several complaints received by the COGCC about odor occurring in the Erie area south of the Crestone Peak Resources, Waste Connection drilling pad.On 5-16-2017, I performed a complete site inspection of the Waste Connection location and the neighborhoods south and southeast of the drilling pad. At the time of inspection, I observed Ensign drilling rig 153 on the location performing drilling operation for Crestone Peak Resources. I reviewed location records, which did not show any abnormal drilling conditions at the time of the complaints.As part of my inspection process I drove thru the neighborhoods indicated on the complaints. I did not detect any odors in the neighborhood at the time of my inspectionAll information reviewed and site inspection information were submitted to the complaint specialist for further review.No violations of COGCC rules were observed at the time of the inspection.

Corrective Action:

Date:

Well Drilling**Rig:** Rig Name: ENSIGN 153 Pusher/Rig Manager: BUDDY BURKEPermit Posted: Yes Access Sign: Yes**Well Control Equipment:**Pipe Ram: YES Blind Ram: YES Hydril Type: YESPressure Test BOP: Pass Test Pressure PSI: Safety Plan: YES**Drill Fluids Management:**Lined Pit: Unlined Pit: Closed Loop: YES Semi-Closed Loop: Multi-Well: YES Disposal Location: WASTE CONNECTIONComment:

Corrective Action:

Date:

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): YES	
Comment:	
Pilot: ON	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Waddles	Pass	Vehicle Tracking	Pass	
Compaction	Pass	Compaction	Pass	Covering Materials	Pass	
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT