



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type:	#		corrective date
Comment: APPROX 32' SOUND WALLS SURROUND LOCATION FOR SOUND MITIGATION			
Corrective Action:			Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type	Field Flare		
Comment: NOT IN USE AT TIME OF INSPECTION			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 434370 Type: WELL API Number: 123-38122 Status: DG Insp. Status: DG

**Complaint**

Comment: [Complaint Received May 22, 2017](#)

Field Inspector Assigned: Jason E. Gomez

Complaint Received:

Date: 5-22-2017 Time 0800 Hrs

Contacted by Complaint Specialist per Complaint Response forms

Date: 5-22-2017

Well Number#: Location #: 434375

Inspection Document #: 674200077

Nature of complaint: Odor

Field Inspector Actions:

On 5-22-2017, I was contacted by complaint specialist Megan Adamczyk in reference to several complaints received by the COGCC about odor occurring in the Erie area south of the Crestone Peak Resources, Waste Connection drilling pad.

On 5-22-2017, I performed a complete site inspection of the Waste Connection location and the neighborhoods south and southeast of the drilling pad. At the time of inspection, I observed Ensign drilling rig 153 on the location performing drilling operation for Crestone Peak Resources. I reviewed location records, which did not show any abnormal drilling conditions at the time of the complaints.

As part of my inspection process I parked in the neighborhood at the end of Alpine Dr. and Crestview for approx. 1hrs. I did not detect any odors during this time.

All information reviewed and site inspection information were submitted to the complaint specialist for further review.

No violations of COGCC rules were observed at the time of the inspection.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Well Drilling**

**Rig:** Rig Name: ENSIGN 153 Pusher/Rig Manager: PETER SANTOS  
 Permit Posted: \_\_\_\_\_ Access Sign: Yes

**Well Control Equipment:**

Pipe Ram: YES Blind Ram: YES Hydril Type: YES  
 Pressure Test BOP: Pass Test Pressure PSI: \_\_\_\_\_ Safety Plan: YES

**Drill Fluids Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: YES Semi-Closed Loop: \_\_\_\_\_  
 Multi-Well: YES Disposal Location: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Covering Materials	Pass	
Gravel	Pass	Waddles	Pass	Vehicle Tracking	Pass	
Ditches	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT