

## Inspection Photos

Location Number: 336202



**Rengler 39-22 wellhead from east.**



**Painted and capped flowline riser at Rengler 39-22 wellhead**

## Inspection Photos

Location Number: 336202



**HSR – Hartell 16-22A Wellhead with capped and painted riser. From north**



**Tank battery from east**

## Inspection Photos

Location Number: 336202



**Separators and meter runs from northeast**



**Riser north of Rengler separator  
40.20676, -104.75459**

## Inspection Photos

Location Number: 336202



**Painted and capped risers (2X) north side of Hartell separator, 40.20676, -104.75459**



**Two risers labeled for the Kuersteiner 9-22A  
40.20676, -104.75456**