

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/22/2017

Submitted Date:

05/22/2017

Document Number:

679902563**FIELD INSPECTION FORM**

Loc ID 337808 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 86610Name of Operator: CAERUS WASHCO LLCAddress: 1001 17TH STREET - STE #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name   | Phone                | Email                           | Comment               |
|----------------|----------------------|---------------------------------|-----------------------|
| Grant, Rachael | 918-585-1650 ext 212 | regulatory@foundationenergy.com |                       |
| McKee, Michael | 720-880-6322         | mmckee@caerusoilandgas.co       | EHS (all Inspections) |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 288757      | WELL | PR     | 08/01/2008  | GW         | 125-10615 | KNODEL 11-16  | PR          |

**General Comment:**

**Location**

|                    |                             |       |  |
|--------------------|-----------------------------|-------|--|
| <b>Lease Road:</b> |                             |       |  |
| Type               | Access                      |       |  |
| comment:           | Gravel road through pasture |       |  |
| Corrective Action  |                             | Date: |  |

Overall Good: ☒

|                      |                    |       |  |
|----------------------|--------------------|-------|--|
| <b>Signs/Marker:</b> |                    |       |  |
| Type                 | WELLHEAD           |       |  |
| Comment:             | Lease sign by unit |       |  |
| Corrective Action:   |                    | Date: |  |

|                           |       |  |  |
|---------------------------|-------|--|--|
| Emergency Contact Number: |       |  |  |
| Comment:                  |       |  |  |
| Corrective Action:        |       |  |  |
|                           | Date: |  |  |

Overall Good: ☒

|                |      |        |  |  |  |
|----------------|------|--------|--|--|--|
| <b>Spills:</b> |      |        |  |  |  |
| Type           | Area | Volume |  |  |  |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

|                    |                                       |       |  |
|--------------------|---------------------------------------|-------|--|
| <b>Fencing/:</b>   |                                       |       |  |
| Type               | PUMP JACK                             |       |  |
| Comment:           | Metal panels around unit and wellhead |       |  |
| Corrective Action: |                                       | Date: |  |

|                           |                |       |                 |
|---------------------------|----------------|-------|-----------------|
| <b>Equipment:</b>         |                |       | corrective date |
| Type: Ancillary equipment | # 1            |       |                 |
| Comment:                  | Electric panel |       |                 |
| Corrective Action:        |                | Date: |                 |
| Type: Pump Jack           | # 1            |       |                 |
| Comment:                  | Sentry unit    |       |                 |
| Corrective Action:        |                | Date: |                 |
| Type: Deadman # & Marked  | # 4            |       |                 |
| Comment:                  |                |       |                 |
| Corrective Action:        |                | Date: |                 |
| Type: Prime Mover         | # 1            |       |                 |
| Comment:                  | Electric motor |       |                 |
| Corrective Action:        |                | Date: |                 |

|                 |    |  |  |
|-----------------|----|--|--|
| <b>Venting:</b> |    |  |  |
| Yes/No          | NO |  |  |
| Comment:        |    |  |  |

|                    |  |       |  |
|--------------------|--|-------|--|
| Corrective Action: |  | Date: |  |
| <b>Flaring:</b>    |  |       |  |
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

| Inspected Facilities |   |       |      |             |           |         |    |               |    |
|----------------------|---|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 288757  | Type: | WELL | API Number: | 125-10615 | Status: | PR | Insp. Status: | PR |
| Producing Well       |   |       |      |             |           |         |    |               |    |
| Comment:             | Producing. Casing production. Central meter run for (KNODEL 11-16, 12-16, 13-16, 14-16) 1400' S @ 39.71128/-102.08128 |       |      |             |           |         |    |               |    |
| Corrective Action:   |   |       |      |             |           |         |    | Date:         |    |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction       | Pass            | Compaction              | Pass                  |               |                          |         |
|                  |                 | Gravel                  | Pass                  |               |                          |         |
| Gravel           | Pass            | Check Dams              | Pass                  |               |                          |         |

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT