

Location

Lease Road:			
Type	Access		
comment:	Graveled two track through pasture		
Corrective ActionL		Date:	

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign by unit. Add sticker to show current operator		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date:	<input style="width: 80%;" type="text"/>

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Metal panels around unit and wellhead		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 252718 Type: WELL API Number: 125-06594 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Casing production. Central meter run for \(State 16-9-1, 16-16\) 1480' N @ 39.71022/-102.06584](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment: [Access is partially grassed over](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT